

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Metro South Morang

Metro South Morang South Morang

Contract No: P3591

## Callouts:

Date of Call: 31-10-2018 17:38:00 Time of Arrival: 31-10-2018 18:38:00 Rectification Time: 31-10-2018 20:30:00 Time of Departure: 31-10-2018 20:35:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): See Fault Description

For Lift(s): 1

For Floor(s): g

Call Description: Lift phones not working

Order Number: 0

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Tested lift phones and lift phones were intermittently not working on top landing and not working in lift and bottom landing.\r\nFound platfo level phone faulty and causing can bus faults on other units.\r\nDisconnect platform level and other phoned worked perfectly.\r\nOrganizing new phone from supplier platform level first thing in morning when supplier is open. All phones except platform level working, station staff notified.

0

Part Required: New slave unit to be picked up in morning from supplier

Service Technician Report Customer

Zane Tregurtha