

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

William Angliss Institute (Building C - 555 La Trobe St) 555 La Trobe St Melbourne (Building C) Contract No: P3175

## Callouts ID:

Date of Call: 29-10-2018 7:19:00 Time of Arrival: 29-10-2018 7:34:00 Rectification Time: 29-10-2018 7:58:00 Time of Departure: 29-10-2018 8:28:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 1

For Floor(s): G

Call Description: SWP on G.

Order Number: TBC

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): Slack Rope Tripped

Work Action (CORRECTION): Reset/Adjust Switch

Work Description: Lift SWP on G. Found Slack rope switch tripped. Released passenger, reset and adjust switch. Tested. Ok.

Part Required: No Parts Required

Service Technician Report Customer

James Grey Passenger