

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Kingsgate Hotel
131 King St Melbourne
Contract No: P3249

## Callouts:

Date of Call: 18-12-2018 9:10:00 Time of Arrival: 18-12-2018 9:10:00 Rectification Time: 18-12-2018 11:10:00 Time of Departure: 18-12-2018 11:10:00

## **CALLOUTS DETAILS**

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 2

For Floor(s): All

Call Description: Lift shutdown previous night

Order Number: Nil

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): Faulty Contactor

Work Action (CORRECTION): Replace/Repair Reply or Contactor

**Work Description:** Lift shutdown previous night. Found KMB contactor to be sticking/going high resistance. \r\nReplaced contactor with new and ran to test. \r\ terminate landing CAN bus plug. \r\nTested. Ok.

Part Required: 18.5kw, 230vAC Contactor

Service Technician Report Customer

James Grey Building Manager