

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Orrong Towers
723 Orrong Rd Toorak
Contract No: P3186

Callouts: 22310

Date of Call: 16-11-2018 15:09:00 Time of Arrival: 16-11-2018 15:30:00 Rectification Time: 16-11-2018 16:30:00 Time of Departure: 16-11-2018 16:30:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): Noisy

For Lift(s): 1

For Floor(s): \*

Call Description: making a clunging sound as it goes up and down.

Order Number: \*

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Door cam fixing bracket had broken off of door, causing cam to clip landing sills. Re-attached bracket, realigned cam. Returned to service. Tok

Part Required: No Parts Required

Service Technician Report Customer

Nathan Downton Rob (gough partners) 1300 46844 / 0433 143 664