

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Cooke Crt 3, Richmond (Building D - East Block) 3 Cooke Crt Richmond (Building D - East Block)

Contract No: P3550

## Callouts:

Date of Call: 02-11-2018 8:00:00 Time of Arrival: 02-11-2018 8:20:00 Rectification Time: 02-11-2018 8:45:00 Time of Departure: 02-11-2018 9:00:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): East lift

For Floor(s): 5

Call Description: Lift shutdown from previous night call. Faulty governor switch.

Order Number: 15405

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): Govenor Tripped

Work Action (CORRECTION): See Work description

Work Description: Replaced governor switch and returned to service. Tested ok.

Part Required:

Service Technician Report Customer

Nathan Downton