

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Pran Central Apartments
220 Commercial Rd Prahran
Contract No: P3279

Callouts: 22716

Date of Call: 27-12-2018 9:59:40 Time of Arrival: 27-12-2018 10:05:00 Rectification Time: 27-12-2018 10:30:00 Time of Departure: 27-12-2018 10:45:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 2

For Floor(s): 2-3

Call Description: people stuck in lift

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): Faulty Contactor

Work Action (CORRECTION): Replace/Repair Reply or Contactor

Work Description: Lift 2 SWP on m, found high resistance contact on the brake contactor not allowing brake to lift \r\nReplaced contact and tested lift

Part Required: No Parts Required

Service Technician Report Customer

Dwain Sanderson Shelle 0412064857