

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Albert Redevelopment
140 Albert Road South Melbourne
Contract No: W3688

Callouts: 22462

Date of Call: 03-12-2018 10:25:39 Time of Arrival: 03-12-2018 10:30:00 Rectification Time: 03-12-2018 11:30:00 Time of Departure: 03-12-2018 12:00:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): See Fault Description

For Lift(s): 2

For Floor(s): .

Call Description: new inductor stack.

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Replaced faulty inductor vaccum water off roof top

Part Required: No Parts Required

Service Technician Report Customer

Brad Stellini