

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Keilor Rd 76-78, Essendon North
76-78 Keilor Rd Essendon North
Contract No: B3452

Callouts: 22243

Date of Call: 09-11-2018 10:43:51 Time of Arrival: 09-11-2018 11:15:00 Rectification Time: 09-11-2018 12:00:00 Time of Departure: 09-11-2018 12:15:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 1

For Floor(s): In car

Call Description: panel in lift is loose **Order Number:** WO#0811187130

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Lift call operating panel knocked out of place. Replace locating screw and remounted.

Part Required: No Parts Required

Service Technician Report Customer

Marek Torrico