

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Jones Lang LaSalle
401 Collins St Melbourne
Contract No: P3216

Callouts: 22255

Date of Call: 12-11-2018 10:19:32 Time of Arrival: 12-11-2018 10:38:00 Rectification Time: 12-11-2018 12:30:00 Time of Departure: 12-11-2018 12:35:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 1

For Floor(s): Bsaement

Call Description: person stuck in the lift.

Order Number: .

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Error 35 \r\nreplaced KMB relay \r\nchecked operation .\r\n\r\nchecked operation

Part Required: 1 seimens 5.5 kw\r\n220ac coil

Service Technician Report Customer

Robert Pelle Christian 0401 401 196