

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Metro Dandenong

Metro Foster Street Dandenong

Contract No: W3677

Callouts:

Date of Call: 07-11-2018 18:05:00 Time of Arrival: 07-11-2018 19:05:00 Rectification Time: 07-11-2018 19:55:00 Time of Departure: 07-11-2018 20:20:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 2

For Floor(s): 1 (Platform)

Call Description: Lift 2 stuck in basement

Order Number: 658001

DESCRIPTION OF WORK

Fault Found (CAUSE): Door Lock Faulty

Work Action (CORRECTION): Adjust Doors/Locks

Work Description: Lift ooo on level 1 (Platform). Error code 54. Found voltage drop in landing door circuit, checked, cleaned and adjusted all landing and car de Ran lift continuously to test. Ok.

Part Required: No Parts Required

Service Technician Report Customer

James Grey Daniel at Dandy