

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Henry St 71, Kensington
71 Henry St Kensington
Contract No: P3503

Callouts:

Date of Call: 25-12-2018 20:37:00 Time of Arrival: 25-12-2018 22:20:00 Rectification Time: 25-12-2018 22:40:00 Time of Departure: 25-12-2018 23:00:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 1

For Floor(s): 2

Call Description: Swp but passenger got out

Order Number:

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Middle dz Inductor sticking\r\nLift wasnt making floors then automatically reset at basement \r\nClean and free up inductor and test inductor operation throroughly with magnet before returning to service and testing\r\nIf faults again inductor to be replaced

Part Required: No Parts Required

Service Technician

Report Customer

Matt Grieger