

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Trak Centre
443 Toorak Rd Toorak
Contract No: P3166

Callouts:

Date of Call: 15-12-2018 8:09:00 Time of Arrival: 15-12-2018 10:30:00 Rectification Time: 15-12-2018 10:55:00 Time of Departure: 15-12-2018 11:30:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 2

For Floor(s): G

Call Description: Lift not running

Order Number: Nil

DESCRIPTION OF WORK

Fault Found (CAUSE): Faulty Relay

Work Action (CORRECTION): Strip and Bebuild

Work Description: Drive not receiving run signal. Strip and clean multiple contacts in circuit. Run to test. Ok.

Part Required: No Parts Required

Service Technician Report Customer

James Grey Oliver