

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Swiss Club of Victoria
89 Flinders Lane Melbourne
Contract No: P3466

Callouts: 22417

Date of Call: 27-11-2018 15:57:02 Time of Arrival: 27-11-2018 10:15:00 Rectification Time: 27-11-2018 11:20:00 Time of Departure: 27-11-2018 11:50:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): 1

Call Description: passenger lift is out of order

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): Fuse Blown

Work Action (CORRECTION): Replace/Reset Fuse

Work Description: 1st floor landing button bridging piece loose causing short circuit. Reglued bridging piece in position and checked operation.

Part Required: No Parts Required

Service Technician Report Customer

Graeme Gathercole Roger 9650 1196