

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Tabcorp Park
2 Ferris Road Melton
Contract No: P3564

Callouts:

Date of Call: 03-12-2018 9:45:00 Time of Arrival: 03-12-2018 9:45:00 Rectification Time: 03-12-2018 10:30:00 Time of Departure: 03-12-2018 11:25:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 2

For Floor(s): All

Call Description: LIFT SHUTDOWN

Order Number: Nil

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): Adjust Brake/Swithces

Work Description: Lift shutdown over weekend. Found brake monitoring input to not be switching all of the time. Re-terminate brake switch inputs to main boa and on switch mechanism. Adjust point of contact and lift on brake arms. Conduct full speed brake tests, ok. Ran to test, ok.

Part Required: No Parts Required

Service Technician Report Customer

James Grey Building Manager