

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Tintern Ave 5, Toorak
5 Tintern Ave Toorak
Contract No: 3052

## Callouts:

Date of Call: 15-12-2018 14:13:00 Time of Arrival: 15-12-2018 15:35:00 Rectification Time: 15-12-2018 16:15:00 Time of Departure: 15-12-2018 16:20:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 1

For Floor(s): ground

Call Description: reported lift out of service no passengers

Order Number: .

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: error 82 \r\nlift on ground floor doors closed not responding \r\ncleared fault run tested ok\r\nchecked operation.

Part Required: No Parts Required

Service Technician Report Customer

Robert Pelle Holliger