

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
100 Albert Road
100 Albert Road South Melbourne 3205
Contract No: P3614

Callouts: 22729

Date of Call: 28-12-2018 15:48:34 Time of Arrival: 28-12-2018 16:00:00 Rectification Time: 28-12-2018 16:30:00 Time of Departure: 02-01-2019 16:40:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): O.O.O

For Lift(s): 2

For Floor(s): g

Call Description: Lift is stuck

Order Number: .

DESCRIPTION OF WORK

Fault Found (CAUSE): Faulty Contactor

Work Action (CORRECTION): Replace/Repair Reply or Contactor

Work Description: Lift 2 000 on g found a high resistance contact on the back of m which caused CX and C to not come in, cleaned contact and tested lift opera

Part Required: No Parts Required

Service Technician Report Customer

Dwain Sanderson Maureen Greene (through email)