

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:

Box Hill Town Hall
1022 Whitehorse Rd Box Hill
Contract No: 3472 - B505

Callouts: 22232

Date of Call: 08-11-2018 11:33:48 Time of Arrival: 08-11-2018 11:45:00 Rectification Time: 08-11-2018 14:30:00 Time of Departure: 08-11-2018 15:00:00

CALLOUTS DETAILS

Reported Fault (COMPLAINT): Button/Indicator Not Working

For Lift(s): 2,3
For Floor(s): *

Call Description: lift 3 has an intermittent high pitch sound, type of alarm\r\ndumb waiter service lift, the call/arrival button stays lit up and buzzes continually we the lift is on lower ground level.

Order Number: 126125

DESCRIPTION OF WORK

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Lift 3 ARD battery low voltage alarm sounding. Reset ARD. Battery began charging as normal. Returned to service.\r\n\r\nDumb waiter groufloor buzzer constantly on when car is at floor. Suspect faulty diode. Disconnected buzzer while new diode is sourced. Returned to service.

Part Required: No Parts Required

Service Technician Report Customer

Nathan Downton