

Unit 3 / 260 Hyde St YARRAVILLE VIC 3013 1300161740 info@unitedlifts.com.au

Service Address:
Knox City Apartments
337 Stud Rd / 400-408 Burwood Road Wantirna South
Contract No: P3244

## Callouts:

Date of Call: 12-11-2018 21:51:00 Time of Arrival: 12-11-2018 10:40:00 Rectification Time: 12-11-2018 22:55:00 Time of Departure: 12-11-2018 23:25:00

## CALLOUTS DETAILS

Reported Fault (COMPLAINT): S.W.P

For Lift(s): 1

For Floor(s): 3

Call Description: 800mm below level 3

Order Number: 1

## **DESCRIPTION OF WORK**

Fault Found (CAUSE): See Work Description

Work Action (CORRECTION): See Work description

Work Description: Fault code 20, checked the leveling inductors and slowdown limit, tightened the connections both at the juction box and in the car top box terminal ran lift between floors

1

Part Required: No Parts Required

Service Technician Report Customer

Steven Johnson