

Verification metrics

Plans need numbers that leadership and engineers share

Bars that matter

- Pass rate below the bar means instability, you cannot trust green stories
- Coverage percent below goal means unfinished plan risk
- Bug escapes above zero at a sev-one bar usually stop the gate
- Levels good, warn, and bad are how you talk without drowning in raw dumps

Browser lab

Digital Design and Verification Platform

HomeTools

Home / Tools / Verification metrics board

INTERACTIVE TOOL

Verification metrics board

Document-aid literacy: **pass rate**, **coverage %**, and **bug escape** as a closure dashboard (concept). Starter: all bars met — board HEALTHY.

Starter example: pass 98%, coverage 95%, escapes 0 — board HEALTHY.

Load starter example

Challenges 0 / 22 cleared

Quiz: **pass rate**: Pass rate tracks...

☐ the fraction of regression jobs that pass versus a bar

☐ only synthesis area

☐ GTKWave cursor count

☐ Makefile PHONY targets

Show hint

Check

Next

Idle

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

Core ideas

pass rate

Regression green % vs bar.

coverage %

Plan hit rate vs goal.

bug escape

Late / field sev-1 count.

HEALTHY

Every metric meets its bar.

Lab

SCENARIO

all good

Load preset

Apply level

Scan board

Demo escape

Explain

Reset

Board HEALTHY — pass + coverage + escapes meet bars

Lab starter

Planning docs practice

- Write three metric names with a numeric bar each for a fictional milestone
- Mark today's sample good, warn, or bad
- If any is bad, write the first action you would take this week

Pitfalls to watch

- Do not call the program healthy because CI ran once
- Do not ignore escape counts when coverage is high
- Do not change bars silently mid-milestone
- And do not track twenty vanity metrics, three honest bars beat a dashboard museum

Your turn

- Complete the checklist for at least one track, preferably both
- Set or interpret three bars, then take the quiz and continue to CI and farm flow