

VIP handoff

A VIP is not handed off when the agent compiles once

Docs, API, self-test

- Docs pack means README, quickstart, examples, and known limits
- API surface means sequences, config knobs, callbacks
- Self-test means a shipped smoke or self-check that runs without the integrator's full SoC
- Met, open, fail, and waived work like the sign-off gate

Browser lab

Digital Design and Verification Platform

HomeTools

Home / Tools / VIP handoff checklist

INTERACTIVE TOOL

VIP handoff checklist

Document-aid literacy: deliver **docs**, **API**, and **self-test** before handing a VIP to another team. Starter: all three met — handoff **READY**.

Starter example: docs_pack, api_surface, and self_test all **met** — handoff **READY**.

Load starter example

Challenges 0 / 22 cleared

Quiz: docs: VIP docs for handoff should include...

☐ README / quickstart / examples / known limits for consumers

☐ only a Makefile PHONY

☐ place-and-route scripts

☐ font choices

Show hint

Check

Next

Idle

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

Core ideas

docs

README, quickstart, examples, limits.

API

Sequences, config, callbacks, vif.

self-test

Standalone smoke that proves it runs.

READY

All met or waived — safe to hand off.

Lab

SCENARIO

Lab starter

Planning docs practice

- For a fictional UART VIP, list the three deliverables and one artifact name under each
- Mark any gap you would refuse to hand off with
- Optional: note which protocol course module already practiced VIP anatomy so this handoff

Pitfalls to watch

- Do not ship without a self-test
- Do not call undocumented knobs an API
- Do not waive docs silently
- And do not confuse handoff ready with chip sign-off

Your turn

- Complete the checklist for at least one track, preferably both
- Drive a handoff board to ready or name the blocker