

Phase I Environmental Site Assessment - Executive Summary

1200 Harbor Way, Everett, Massachusetts 02149 | Prepared for Acme Bank | July 29, 2026 | Northbank Environmental Consultants

1. Purpose and Scope

This assessment was performed in accordance with ASTM E1527-21 to identify recognized environmental conditions in connection with the acquisition financing of the property. The scope included a site reconnaissance, interviews, a review of historical sources and regulatory databases, and a review of prior reports.

2. Findings

Area	Finding
Recognized environmental conditions	None identified
Historical recognized environmental conditions	None identified
Controlled recognized environmental conditions	None identified
De minimis conditions	Minor staining at the truck fueling pad; housekeeping item only
Regulatory database listings	Property not listed; one closed leaking underground storage tank site 0.4 miles east, downgradient

3. Conclusions and Recommendations

No recognized environmental conditions were identified. No further investigation is recommended. The consultant recommends routine maintenance of the fueling pad and confirmation that the current spill prevention plan remains on file.

This synthetic environmental report is designed for loan origination demonstrations. Names, addresses, amounts, and terms are fictional and are not financial or legal advice.