

Firmware V6.0.1

ND-4M-D28L · 4 MP LumaNight dome

Improvements

1. Faster boot and reconnection after power loss.
2. Improved detection accuracy in rain and snow.
3. TLS 1.3 by default for all web and API traffic.

Fixes

1. Resolved time drift when NTP is unreachable.
2. Fixed an issue where schedules were not applied after a restore.

Before you upgrade

1. Export the configuration.
2. Do not remove power during the upgrade (about 3 minutes).