

# Firmware V6.0.1

NB-16M-P4 · 16 MP PanoSight 180° multi-sensor

## Improvements

1. Faster boot and reconnection after power loss.
2. Improved detection accuracy in rain and snow.
3. TLS 1.3 by default for all web and API traffic.

## Fixes

1. Resolved time drift when NTP is unreachable.
2. Fixed an issue where schedules were not applied after a restore.

## Before you upgrade

1. Export the configuration.
2. Do not remove power during the upgrade (about 3 minutes).