v52 corner diagnosis: failure begins before the safe curve expires

Recorded v52: route refresh, solve failure, then command stop







Corner geometry and native safety probes