

1. What gain parameters did you end up using for your PI controller?

$K_p = 5$, $K_i = 5$

2. Describe the response of the system to parameter changes.

Some undershoot and overshoot present when changing from one RPM to another, this is likely due to the K_p gain. Some steady state error present when staying at a specific RPM, this is due to the K_i value, and further tuning could reduce this

3. Include the plots of the data collected, including the gain parameters (K_i , K_p)



