DANLAW		FIR	
Product Code	DL545	Centralised ID	DTIL25030023
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	20-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030023	
2	Date of communication failure	2025-03-01 09:05:00	
3	Device Model	DL545	
4	Defective device PSN	2307246150	
5	VIN Number	MB1TSKHD3PRFM5881	
6	Device IMEI	564324567890876	
7	Device CCID	8991643013472648270	
8	Date of Sale of Device	13-03-2025	
9	S Trigger Date	05-03-2025	
10	C Trigger Date	19-03-2025	
11	Commercial Expiry date	04-03-2025	
12	Active Profile (BSNL/Airtel/Dual)	BSNL	
13	Vehicle Type / Model	LCV	
14	Failure Location Plant/ Field- Customer Address UTTARPRADESH		
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Anil	
18	Reason for Replacement/Repair	Repair	
19	Darby Last communication date	2025-03-01 09:05:00	
20	Device Replacement request Initiation date	2025-03-20 09:13:58	
21	Returnable / Non-Returnable	Repair	

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Anil	20-03-2025	Anil
Service Manager	upendram@danlawtech.com	N/A	upendram@danlawtech.com
Sales & Service Head	Rajendran Subramanian	2025-03-20 09	Rope