DANLAW		FIR	
Product Code	DL548	Centralised ID	DTIL25030020
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	19-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030020	
2	Date of communication failure	2025-03-13 06:21:00	
3	Device Model	DL548	
4	Defective device PSN	2307246150	
5	VIN Number	MB1TSKHD3PRFM5881	
6	Device IMEI	867192067965498	
7	Device CCID	8.991643013472648e+19	
8	Date of Sale of Device	03-08-2023	
9	S Trigger Date	18-08-2023	
10	C Trigger Date	14-09-2023	
11	Commercial Expiry date	12-01-2026	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	T&T	
14	Failure Location Plant/ Field- Customer Address GUJARAT TO JODHPUR		
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Anil	
18	Reason for Replacement/Repair	Repair	
19	Darby Last communication date	2025-03-13 06:21:00	
20	Device Replacement request Initiation date	2025-03-19 09:00:46	
21	Returnable / Non-Returnable	Repair	

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Anil	19-03-2025	Anil
Service Manager	kunal@danlawtech.com	2025-03-19 09	ପ <b>୍ୟପ2ରି</b> I@danlawtech.com
Sales & Service Head	Rajendran Subramanian	2025-03-19 09	C Rope