## **Device Repair Request**

Name: DL545 Jira SRN ID: ACS-6583-1127

Customer: AL Format Req. No.: ASS/011/08/21 Ver-2

Document by: After Sales Support TeamDate: 13-03-2025

SL No Description Details

1 Service Request Number ACS-6583 2 Date of communication failure 13-03-2025

3 Device Model DL545

4 Defective device PSN 2207222006

5 VIN Number MB1NEKLD9NPBU1435

6 Device IMEI 867624067250414

7 Device CCID 89916420534722378909

 8
 Date of Sale of Device
 23-07-22 11:53

 9
 S Trigger Date
 03-01-23 0:01

 10
 C Trigger Date
 13-02-23 13:33

 11
 Commercial Expiry date
 01-07-25 5:30

 12
 Active Profile (BSNL/Airtel/Dual)
 Single Airtel

13 Vehicle Type / Model G91 sleeper suspended non tilt

14 Failure Location Plant/ Field- Customer Address WM-Rabinarayan behera-97771 40132■SHREE GANESH AUTOI

15 Kilometers/Hours 139788 KM

16 Main Battery Voltage 24

17 Service Engineer Name Gayadhar
 18 Service Engineer Comment Sim Issue
 19 Reason for Replacement/Repair Sim Issue

20 Engineering Team Comment

21 DEAL Plant Team Comment

22 Darby Last communication date 20-02-25 10:46

23 Updated request in Darby

Device Replacement request Initiation date
 Returnable / Non-Returnable

## Approved By:

Initiated by- Service Eng.: Gayadhar 13-03-2025 Gayadhar

Recommended by- Engineering:

Service Manager: Kunal 13-Mar-25 Kunal

Sales & Service Head: Rajendran Subramanian 16-Mar-25