DANLAW		FIR	
Product Code	DL545	Centralised ID	DTIL25030019
Customer	O.E	Format Req. No.	ASS/011/08/21 Ver-2
Document by	After Sales Support Team	Date	19-03-2025

SL No.	Description	Details	
1	Service Request Number	DTIL25030019	
2	Date of communication failure	2025-02-22 14:55:00	
3	Device Model	DL545	
4	Defective device PSN	2209121081	
5	VIN Number	MB1A5CHD0NEDJ3859	
6	Device IMEI	867624067735950	
7	Device CCID	8.991642053472254e+19	
8	Date of Sale of Device	16-09-2022	
9	S Trigger Date	20-10-2022	
10	C Trigger Date	10-01-2023	
11	Commercial Expiry date	29-05-2025	
12	Active Profile (BSNL/Airtel/Dual)	Airtel	
13	Vehicle Type / Model	Haulage	
14	Failure Location Plant/ Field- Customer Address SAILEMTOAHMEDABAD		
15	Kilometers/Hours	Kilometers	
16	Main Battery Voltage	24.0	
17	Service Engineer Name	Anil	
18	Reason for Replacement/Repair	Repair	
19	Darby Last communication date	2025-02-22 14:55:00	
20	Device Replacement request Initiation date	2025-03-19 08:46:04	
21	Returnable / Non-Returnable	Repair	

Approved By:	Name	Date	Signature
Initiated by- Service Eng.	Anil	19-03-2025	Anil
Service Manager	kunal@danlawtech.com	2025-03-19 08	4605121@danlawtech.com
Sales & Service Head	Rajendran Subramanian	2025-03-19 08	2 Rope