ID	Name	2023	2024				2025				
		Q4	Q1	Q2	Q3	Q4	Q1	Q2	Q3	Q4	Q1
1	▼ Automated Asset Oversight and Maintenance										
2	▼ Project Initiation		0								
39	Define Project Objectives and Scope		1								
3	Project Kickoff Meeting		1								
46	Meeting Team		1								
5	▼ Preliminary Research										
6	Literature Review										
7	Market Research										
8	Feasibility Study										
9	Review and Summarise										
10	▼ Data Collection and Preprocessing										
14	Define Image Collection Protocol										
12	Image Collection										
13	Image Labelling										
41	Image Preprocessing and Quality Enhance										
11	▼ Model Development and Training										
15	Choose and Implement Preprocessing Met										
16	Model Design and Train										
18	Model Optimization and Hyperparameter T										
19	Validate Model Performance										
20	▼ Unsupervised Anomaly Detection Integration										
21	Integrate Unsupervised Learning Techniques										
22	Test and Validate Anomaly Detection										
25	▼ System Integration and Testing										
42	Develop Integration Plan										
28	▼ User Interface Design										
29	Design UI for Inspection Results										
30	Review and Refine UI Design										
47	Create UI										
26	Integrate Trained Models with Existing Syst										
27	Conduct Unit Testing										
43	Conduct Integration Testing										
44	Conduct End-to-End Testing										
45	Conduct Performance Testing										
31	 Deployment and Monitoring 										
32	Deploy Integrated System										
33	Monitor System Performance										
48	Revision/Revisit										
34	▼ Final Documentation and Reporting										
35	Prepare Project Documentation										
36	Create Final Project Report										
37	▼ Project Closure										
38	Conduct Project Review and Evaluation										