

Component mounting procedure manual

M5Stamp unimplemented version




M5Stamp implementation version




Round LCD implementation

Back side of board




Apply flux in advance

Round LCD front and back




Apply flux in advance

Soldering round LCD




The round LCD must be placed back side; it will not work in reverse.

Align the FPC and land pattern straight and solder in several places.



Furthermore, perform the final soldering



Aligning the positions initially is important, as it will be troublesome to correct them later.

Leave a gap of about 2mm

Be sure to apply insulating tape to the soldered parts.