Wed Oct 14 08:08:50 2020: Establishing connection to DHT sensor

Wed Oct 14 08:08:50 2020: Establishing connection to 8 x 8 display

Wed Oct 14 08:08:50 2020: Establishing connection to 3 axis sensor

Wed Oct 14 08:08:51 2020: Cube Sat Connected!

get_light_value is not a valid command. Please re-enter.

Wed Oct 14 08:09:38 2020: Temp: 26.00C

Wed Oct 14 08:09:38 2020: Humdity: 18.00%

Wed Oct 14 08:10:14 2020: x:-0.85 y:0.00 z:0.65

Wed Oct 14 08:10:14 2020: 3 Axis Temp:24

Wed Oct 14 08:11:10 2020: Light level: 1023

Wed Oct 14 08:14:02 2020: Temp: 26.00C

Wed Oct 14 08:14:02 2020: Humdity: 18.00%

Wed Oct 14 08:14:02 2020: Light level: 1023