
Schematic mks Batatron Pressure Switch 51B11



Notes:

- resistors socket: R30 is the resistor closest to the solder connections
- no guarante for completeness, maybe some connections are missing