

*****Draft Document Only.Task is not yet Completed/Approved.*****

Ref :20260619113318

Date :23-Jun-2026

TASK DETAILS

Site ID : ZKEL23 Site Name : Nungamuwa
Report Category : T S S R B T S5 G Z T Performed By : ZTE

Project Details		
No	Task	Status
1.1	Project Name	5G Expansion Phase 1
1.2	Implementation By	ZTE
1.3	TSSR Type	ZTE 5G
1.4	Project Scope	Swap
1.5	Site Officer	Mr. Asanka Herath
1.6	Vendor Group	ZTE
1.7	Sub-Contractor Company	Asian Star
1.8	Sub-Contractor Officer	Mr. Poorna
1.9	Site Survey Date	2026-06-19
1.10	Site Officer Contact No	0785288583
Site Info		
No	Task	Status
2.1	Address	M.A.S.S.D._Silva-_071843619_/_No._446/2,_Nungamuwa,_Kelaniya
2.2	Longitude	79.9137
2.3	Latitude	6.9643
2.4	Altitude	
2.5	Existing Technology	4G
2.6	Frequency Band	L1800

Site Acc Info		
No	Task	Status
3.1	Operator	Mobitel
3.2	Site Owner Name	Mr. Anura
3.3	Site Owner Contact Number	0714046102
3.4	Access Restriction	No
3.5	Access Restriction Remarks	
3.6	Access on 7 Days	Yes
3.7	Access on 7 Days Remarks	Need Mobitel access permission and informed to Mobitel region, Need BTS pad lock keys
3.8	Access on 24 Hours	No
3.9	Access on 24 Hours Remarks	7.00am to 6.30pm working time
3.10	Prior appointment for access (person to be informed before site access)	Yes
3.11	Prior appointment for access Remarks	Need to inform mobitel region and site owner
3.12	Contact Person	Mr. Indrajith
3.13	Contact Number	0714720071
3.14	Site access key	Mobitel Access Key
3.15	Parking space available	Yes
3.16	Equipment Delivery	Crane
3.17	Safe access to all equipment parts And antennas (lifeline systems, fall arrest systems, anchors.)	No
Site Env Info		
No	Task	Status
4.1	Equipment Location	Building Floor
4.2	Building Floor No	
4.3	Equipment Cabinet	Outdoor Cabinet
4.4	Evidence of Flooding	No
4.5	Distance to Site from Colombo	Less than 50km
4.6	Distance to Site from Colombo (Km)	10

Manual Transport GF

N o	Name	Total Distance(m)	Steep Terrain (m) Less than 45Deg	Steep Terrain (m) Greater Than 45Deg	Terrain Condition (m)Flat	Terrain Condition (m)Rocky	Terrain Condition (m)Hill
1	Green Filed manual handling (m)	N/A	N/A	N/A	N/A	N/A	N/A

Tower Info

No	Task	Status
6.1	Tower Type	1_MP
6.2	Tower Leg Type	Tubular
6.3	Tower Height	6
6.4	Spare Antenna Poles	Yes
6.5	Spare Antenna Poles Count	3
6.6	Spare Plinth Availability	Yes
6.7	Spare Plinth Count	1
6.8	Spare Plinth type	Concrete plinth
6.9	Tower Section Additional Remarks	Distance between bracket 55cm

Tower Section Images1



Tower Section Images2



Tower Section Images3

20260619113318 / KM
/ Tower Section Images3
asianstar_projectuser1
2026-06-19 15:52:40




Power Info Mobitel

No	Task	Status
7.1	Meter Cubical installed	Yes
7.2	Meter Cubical owner	Mobitel
7.3	Existing Commercial Power Source (Mobitel)	Three phase
7.4	Power Source Type	Mobitel CEB
7.5	Mobitel SPD Available Location	near Meter cubical
7.6	Power cable length between Mobitel meter cubical to Mobitel ACDB	25m
7.7	Power cable length between mobitel ACDB to SLT eNodeB	7m
7.8	Existing Free Breaker Qty in mobitel ACDB	2
7.9	Existing Free Breaker Capacity in mobitel ACDB	32A (4 pole breaker)
7.10	ECB available at Mobitel meter cubical	Yes
7.11	Remarks on Mobitel Power Info	

Mobitel Power images 1

20260619113318 / Km
6.9640282 / 79.9137303
Mobitel Power images 1
asianstar_projectuser1
2026-06-19 13:45:09




Mobitel Power images 2

20260619113318 / Km
6.9640282 / 79.9137303
Mobitel Power images 2
asianstar_projectuser1
2026-06-19 13:45:51



Mobitel Power images 3

20260619113318 / Km
6.9640282 / 79.9137303
Mobitel Power images 3
asianstar_projectuser1
2026-06-19 13:47:01



Power Info SLT

No	Task	Status
8.1	Meter Cubical installed	NA
8.2	Meter Cubical owner	NA
8.3	Existing Commercial Power Source (SLT)	NA
8.4	Power Source Type	NA
8.5	Power cable length between meter cubical to SLT SPD	
8.6	Existing AC Power Cable Type	NA
8.7	Accessories in existing SLT SPD enclosure box details (For Outdoor sites only)	

8.8	SLT existing DCDB availability in 19 Inch Rack	
8.9	ECB available at SLT meter cubical	NA
8.10	ECB available at existing SLT plinth	NA
8.11	ECB available (Indoor site only)	
8.12	Remarks on SLT Power Info	

TX Info SLT

No	Task	Status
9.1	TX fiber availability to the site - SLT	N/A
9.2	SLT ODF location	N/A
9.3	Remarks on SLT TX Info	
9.4	Remarks on Mobitel TX Info	

TX Info Mobitel


No	Task	Status
10.1	Mobitel TX Mode	Fiber
10.2	TX fiber availability to the site - Mobitel	Yes
10.3	Mobitel ODF location	Out door
10.4	Mobitel SSR availability	Yes
10.5	Distance between Mobitel CSR and SLT BBU	

Mobitel TX images 1



Mobitel TX images 2



Mobitel TX images 3 											
Manual Transport Special											
No											
1											
2											
3											
4											
5											
Cabinet Info											
	Cabinet No	Cabinet Type	Rectifier type	Rectifier Qty	DC Voltage	Spare Breaker Qty	Spare Breaker Capacity	Battery Type	Battery Physical Condition	Battery Capacity	Battery Qty
	Cabinet 01	TP4820 0A	R4850GI -2U	2	52	1	63A	HU_LI_1 00Ah	Reusable	100	2
No		Task					Status				
12.2		Remarks					Huawei SMU Didplay screen issue				
BBU 01											
No		Task					Status				

13.1	Cabinet No of BBU 01					Cabinet 01			
13.2	Technology of BBU 01					4G			
No	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility	
1	E1FANC	0	Free		4	Free		UEIU	
2		1	Free		5	GTMUb	3		
3		2	Free		6				
4		3	LBBPD2	3	7	UMPTb2		UPEUC	
13.4	Remarks					Huaweiv ATN 950c available			
BBU 02									
No	Task					Status			
14.1	Cabinet No of BBU 02								
14.2	Technology of BBU 02								
No	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility	
1		0			4				
2		1			5				
3		2			6				
4		3			7				
14.4	Remarks								
BBU 03									
No	Task					Status			
15.1	Cabinet No of BBU 01								
15.2	Technology of BBU 01								
No	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility	
1		0			4				
2		1			5				
3		2			6				

4		3			7											
15.4		Remarks														
BBU 04																
No		Task				Status										
16.1		Cabinet No of BBU 01														
16.2		Technology of BBU 01														
No	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility								
1		0			4											
2		1			5											
3		2			6											
4		3			7											
16.4		Remarks														
Antenna Details																
	Sector No	Antenna No	Antenna Type	Tower Leg	Bracket Type	Antenna Height (m)	Antenna Direction	Mechanical Tilt	Spare Port Condition	Port 01	Port 02	Port 03	Port 04	Port 05		
	Sector 0	Antenna 1	TB	Pole	Single Bracket	6	40	0	Good	Used for 1800	Used for 1800	Free For 900	N/A	N/A		
	Sector 1	Antenna 2	TB	Pole	Single Bracket	6	140	0	Bad	Used for 1800	Used for 1800	Free For 900	N/A	N/A		
	Sector 2	Antenna 3	TB	Pole	Single Bracket	6	245	0	Good	Used for 1800	Used for 1800	Free For 900	N/A	N/A		
No		Task				Status										
17.2		Remarks														
Sector Details																
	Sector No	Antenna No	Sector	Electrical Tilt 01	Electrical Tilt 02	Mechanical Tilt	Jump Length	Jump Connect	RRU Type	Filter/Combiner	Feeder Type	Feeder Connect	Feeder Length	Fiber Condition	Power Cable Co	Remarks

								or Type		Type		or			nditi on	
	Sect or 0	Ante nna 1	1800 L18 00_ P	4	4	0	3	DIN- DIN	RRU 3953 w	0	fibre	N/A	15	Goo d	Goo d	N/A
	Sect or 1	Ante nna 2	1800 L18 00_ Q	4	4	0	3	DIN- DIN	RRU 3953 w	0	fibre	N/A	15	Goo d	Goo d	N/A
	Sect or 2	Ante nna 3	1800 L18 00_ R	4	4	0	3	DIN- DIN	RRU 3953 w	0	fibre	N/A	15	Goo d	Goo d	N/A

No	Task	Status
18.2	Remarks	

Existing Site Photo Proof Mobitel

Mobitel Overall Site View




Mobitel Overall Site View 2




Mobitel Overall Site View 3




Mobitel Aerial View 1



Mobitel Aerial View 2



Mobitel Aerial View 3



Mobitel Aerial View 4



Mobitel Exiting Tower View




Mobitel Existing Equipment detail Outlook




Mobitel Existing Equipment detail Outlook 2




Mobitel Existing Equipment detail In look




Mobitel Existing Equipment detail In look 2



Mobitel Existing Equipment detail In look 3




Mobitel Existing Equipment detail In look 4



Mobitel Existing foot print (Back side of the plinth)



Mobitel Existing BBU



Mobitel Existing Batteries



Mobitel Existing sector 01(Overall picture)



Mobitel Existing sector 02(Overall picture)



Mobitel Existing sector 03 (Overall picture)



Mobitel Existing RF antenna sector 01




Mobitel Existing RF antenna sector 02




Mobitel Existing RF antenna sector 03




Mobitel Existing RF antenna azimuth sector 01



Mobitel Existing RF antenna azimuth sector 02




Mobitel Existing RF antenna azimuth sector 03



Mobitel Existing RF antenna Bottom View sector 01

20260619113318 / Km
6.964731 / 79.9142828
Mobitel Existing RF anten
asianstar_projectuser1
2026-06-19 14:58:25



Mobitel Existing RF antenna Bottom View sector 02

20260619113318 / Km
6.9646973 / 79.9139824
Mobitel Existing RF anten
asianstar_projectuser1
2026-06-19 14:59:10



Mobitel Existing RF antenna Bottom View sector 03

20260619113318 / Km
6.9650659 / 79.914002
Mobitel Existing RF anten
asianstar_projectuser1
2026-06-19 14:58:50



Mobitel Existing RRU Sector 01

20260619113318 / Km
6.9646827 / 79.9141842
Mobitel Existing RRU Sect
asianstar_projectuser1
2026-06-19 14:59:44



Mobitel Existing RRU Sector 01 image2

20260619113318 / Km
6.9647935 / 79.9142365
Mobitel Existing RRU Sect
asianstar_projectuser1
2026-06-19 14:59:59



Mobitel Existing RRU Sector 02

20260619113318 / Km
6.9646869 / 79.9142062
Mobitel Existing RRU Sect
asianstar_projectuser1
2026-06-19 15:00:32



Mobitel Existing RRU Sector 02 image2



Mobitel Existing RRU Sector 03



Mobitel Existing RRU Sector 03 image2



Mobitel Existing cable ladder (Vertical)



Mobitel Existing cable ladder (Horizontal)




Mobitel Existing cable ladder (Horizontal) image2



Mobitel Location for Power Source




Mobitel Cable Entry Port Photo



Mobitel Existing Meter (Close Up)



Mobitel Stairs, Elevator and Other Entries




Mobitel All ECB connection point




Mobitel ECB connection point 1




Mobitel Evidence for special manual transport



Mobitel Evidence for special manual transport 2



Mobitel Special Photos to highlight issues (if any)



Mobitel Special Photos to highlight issues (if any) 2



Existing Site Photo Proof SLT

Solution Cabinet Info

No	Task	Status
21.1	Solution Type	W451 cabinet
21.2	Overall solution, scope with special comments	Remove existing TP cabinet, new cabinet install exi.concrete plinth available (building owner requirement also move to free plinth)
21.3	Proposed Equipment Type	Outdoor
21.4	Enough Space for Cabinet	Yes

21.5		Enough Space for BBU Cards						Yes				
21.6		Enough Space for DCDU						Yes				
	Cabine t No	Cabine t Type	Rectifi er type	Rectifi er Qty	DC Volutag e	Spare Breake r Qty	Spare Breake r Capaci ty	Battery Type	Battery Physic al Con dition	Battery Capaci ty	Battery Qty	Cabine t Status
	Cabinet 01	TP4820 0A	R4850 GI-2U	2	52	1	63A	HU_LI_ 100Ah	Reusab le	100	2	Remov ed
	Cabinet 01	ZXDU6 8 W451		6				ZTE_LI _100Ah		100	2	
21.8		Remarks										
Solution BBU 01												
No		Task						Status				
22.1		Solution BBU 01 Status						Removed				
N o	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility				
1		3	LBBPD2	3	7	UMPTb2		UPEUC				
2		1	Free		5	GTMUb	3					
3	E1FANC	0	Free		4	Free		UEIU				
4		2	Free		6							
22.3		Remarks										
Solution BBU 02												
No		Task						Status				
23.1		Solution BBU 02 Status						Swapped				
N o	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility				
1		0			4							
2		1			5	VBPe1p						
3		2	VPDc1		6							
4		3	VSWd1		7							

23.3		Remarks												
Solution BBU 03														
No		Task				Status								
24.1		Solution BBU 03 Status												
No	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility						
1		0			4									
2		1			5									
3		2			6									
4		3			7									
24.3		Remarks												
Solution BBU 04														
No		Task				Status								
25.1		Solution BBU 04 Status												
No	Utility	No	BBU Card	Free Port	No	BBU Card	Free Port	Utility						
1		0			4									
2		1			5									
3		2			6									
4		3			7									
25.3		Remarks												
Solution Antenna Details														
	Sector No	Antenna No	Antenna Type	Tower Leg	Bracket Type	Antenna Height (m)	Antenna Direction	Mechanical Tilt	Spare Port Condition	Port 01	Port 02	Port 03	Port 04	Port 05
	Sector 0	Antenna 1	TB	Pole	Single Bracket	6	40	0	Good	Used for 1800	Used for 1800	Free For 900	N/A	N/A

	Sector 1	Antenna 2	TB	Pole	Single Bracket	6	140	0	Bad	Used for 1800	Used for 1800	Free For 900	N/A	N/A		
	Sector 2	Antenna 3	TB	Pole	Single Bracket	6	245	0	Good	Used for 1800	Used for 1800	Free For 900	N/A	N/A		
No		Task							Status							
26.2		Remarks														
Solution Sector Details																
	Sector No	Antenna No	Sector	Electrical Tilt 01	Electrical Tilt 02	Mechanical Tilt	Jump Length	Jump Connector Type	RRU Type	Filter/Combiner Type	Feeder Type	Feeder Connector	Feeder Length	Fiber Condition	Power Cable Condition	Remarks
	Sector 0	Antenna 1	1800 L1800_P	4	4	0	3	DIN-DIN	R9254E S1800	0	fibre	N/A	15	Good	Good	N/A
	Sector 1	Antenna 2	1800 L1800_Q	4	4	0	3	DIN-DIN	R9254E S1800	0	fibre	N/A	15	Good	Good	N/A
	Sector 2	Antenna 3	1800 L1800_R	4	4	0	3	DIN-DIN	R9254E S1800	0	fibre	N/A	15	Good	Good	N/A
No		Task							Status							
27.2		Remarks							Remove existing RRU, and install the new 9254E S1800 RRU in all 3 sector							
Solution MCW Info																

No	Name	Requirement	Type	Location/direction Qty	Space available	Approval Available	Comments
1	Plinth 1	N/A					
2	Plinth 2	N/A					
3	Plinth 3	N/A					
4	Bracket 1	N/A					
5	Bracket 2	N/A					
6	Bracket 3	N/A					
7	Bracket 4	N/A					
8	Bracket 5	N/A					
9	Bracket 6						
10	Extension bar (Horizontal)	N/A					
11	Extension bar (Vertical)	N/A					
12	Ladder (Horizontal)	N/A					
13	Ladder (Vertical)	N/A					
No		Task			Status		
28.2		MCW Solution Remarks			can use exi.cable ladder, empty 3 exi.single bracket also can used		
Solution Power Info							
No		Task			Status		
29.1		Power Upgrade Required			No		
29.2		Power Upgrade need Phase					
29.3		Power Upgrade remarks			Already 3phase available, existing cable can used		
No	Name	Requirement	Type	Location/direction Qty	Space available	Approval Available	Comments
1	SPD						
2	ACDB						
3	Meter Cubicle						
4	Additional ECBs						

5	ECB Earth Cable						
6	Meter To ACDB Power Cable Length (4X16mm2) (m)						
7	RRU Power Cable Length (m)						
8	RRU Ground Cable Length (m)						
9	DCDU power cable length (m)						
10	ACDB Ground Cable Length (25 mm2) (m)						
11	Battety Cabinet Ground Cable Length (25 mm2) (m)	Yes		2m			
12	BTS and BBU Ground Cable Length (25mm2) (m)	Yes		2m			
13	SPD Pole Ground Cable Length (35 mm2) (m)						
14	GI Pipe from ACDB to BTS (m)	Yes		2m			
15	PVC Pipe from the BTS to RRU (fiber & Power) (m)						

Material Requirment

No	Generic Name	ERP Code	UOM	Qty (Option 01)	Qty (Option 02)	Comments
1	BTS Cabinet	ZT-PWRSUBRAC K-18KW-WR12		Each	1	

Proposed Solution Photos

Sketch List

Punch List		
No	Task	Status
33.1	Punch List 01	
33.2	Punch List 02	
33.3	Punch List 03	
33.4	Punch List 04	
33.5	Punch List 05	
Modification Request		
No	Task	Status
34.1	Modification Request 01	
34.2	Modification Request 02	
34.3	Modification Request 03	
34.4	Modification Request 04	
34.5	Modification Request 05	
Approval		
No	Task	Status
35.1	TSSR Status	
35.2	Process Flow	
35.3	Reassign Officer	
35.4	Final Approval Remarks	

Performed By	AS Project User 1	2026-06-22 14:15:42
---------------------	-------------------	---------------------