### **Software Release Note for 3.08**

### **General**

Product: GPUECP V/W

Software Product: GPUECP.exe Software version number: 3.08 ABB part number: 803025-0308

SPR number: 736 MDS number: 295

Date of Release: December 03,2001

### **Product Summary**

Software/firmware breakdown structure for the product. It is presented as an indented BOM. This release note is for one of the components making up the software breakdown structure. An '\*' indicates this component.

#### GPU2000R

GPU2000R box, V/W configuration

Main Board

#CPU Flash DSP firmware

Monitor firmware

Front Panel

MMI front panel firmware

Communication Board

**AUX-COM** firmware (Standard INCOM)

or -

AUX-MOD firmware (Modbus)

\*GPUECP, V/W configuration

WinFPI

OAT

CurveGen

Note: \* indicates the components covered by this release note.

# indicates the component containing the top level release note, where all of the software components and their version numbers are matched together.

#### Related Documents

Identity	Title	Valid Document Revision
		(change or no change)
RC-1119	GPU2000R INCOM 10 Byte Protocol	Rev 2.2
	GPU2000R Modbus/Modbus Plus, 0X & 1X	Rev 2.3
	Register Document	
	GPU2000R Modbus/Modbus Plus, 4X	Rev 3.3
	Register Document	
	GPU2000R Modbus/Modbus Plus, 4X	Rev 5.3
	Register Document	

Revision	Date	Author	Description		
ABI		ABB A	Automation Inc	Printed: 10/19/2004 Sayed: 12/18/2001	Page 1 of 3

## **Software Release Note for 3.08**

## **New Features and Changes to Existing Functions**

### New Features/Functionality Added

N/A

### Features/Functionality Removed

N/Δ

### Features/Functionality Modified

Fixed a date format displaying 19a1 instead of 2001(CR #394) Added Battery Failure record to Operating Records. (CR# 99)

#### Issues Resolved

CR #394 Date format in Operation Records after setting a clock with GPUecp was 19a1 instead of 2001.

## **Hardware Supported by this Version**

Category	Type Designation
Main Board	smt (surface mount technology)

### **Installation Notes and Restrictions**

#### EPROM Installation or FLASH Download

### Software and Firmware Configuration Supported by this Version

Category	Type Designation	Valid Version
Main board cpu	CPU Flash firmware	V3.30
Main board dsp	DSP firmware	V1.4
Main board bootup rom	Monitor firmware	V2.0
Front panel	MMI front panel firmware	V2.0
Communication card	AUX-COM firmware	V1.7
Configuration & Engineering	WinFPI	V1.0, Build 7
Tools		
Configuration & Engineering	WaveWin	V8.4
Tools		
Configuration & Engineering	CurveGen	V1.0
Tools		

## **Software Release Note for 3.08**

## **Contents of this Version**

## Subsystems

E.g.:

Operating system: Win2000, Win 98, Win95, WinNT

#### **Modules**

File name and version number

# **History (SAR/CRs Retired)**

### Version 3.07 and earlier of GPUECP.exe

Refer to the release documentation for thr specific release,

ABB

Printed: 10/19/2004 Saved: 12/18/2001