
ONLY 2 COMBINATIONS

Sensors: 8 and 11 Test accuracy: 0.63

Test accuracy: 0.643 Test accuracy: 0.637 Test accuracy: 0.625 Test accuracy: 0.621 Mean accuracy: 0.631



Sensors: 12 and 11

Test accuracy: 0.737 Test accuracy: 0.727 Test accuracy: 0.719 Test accuracy: 0.756 Test accuracy: 0.73 Mean accuracy: 0.734 Standard deviation: 0.012



Sensors: 1 and 12

Test accuracy: 0.754 Test accuracy: 0.774 Test accuracy: 0.757 Test accuracy: 0.769 Test accuracy: 0.752 Mean accuracy: 0.761 Standard deviation: 0.009



Sensors: 3 and 7

Test accuracy: 0.843 Test accuracy: 0.836 Test accuracy: 0.846 Test accuracy: 0.842 Test accuracy: 0.843 Mean accuracy: 0.842 Standard deviation: 0.003




Sensors: 8 and 1


Test accuracy: 0.692 Test accuracy: 0.701 Test accuracy: 0.671 Test accuracy: 0.699 Test accuracy: 0.693 Mean accuracy: 0.691 Standard deviation: 0.01



Sensors: 7 and 10

Test accuracy: 0.774 Test accuracy: 0.775 Test accuracy: 0.787 Test accuracy: 0.765 Test accuracy: 0.753 Mean accuracy: 0.771 Standard deviation: 0.011





ONLY 6 COMBINATIONS

Selected sensors: 1, 2, 4, 6, 9, 12


Test accuracy: 0.921 Test accuracy: 0.936 Test accuracy: 0.923 Test accuracy: 0.916 Test accuracy: 0.926 Mean accuracy: 0.924

Standard deviation: 0.007

Set 1,2,4,6,9 and 12

Selected sensors: 2, 4, 6, 5, 9, 3

Test accuracy: 0.929 Test accuracy: 0.941 Test accuracy: 0.939 Test accuracy: 0.937 Test accuracy: 0.934 Mean accuracy: 0.936 Standard deviation: 0.004



Selected sensors: 2, 4, 5, 9, 3, 7

Test accuracy: 0.945 Test accuracy: 0.937 Test accuracy: 0.954 Test accuracy: 0.937 Test accuracy: 0.939 Mean accuracy: 0.942 Standard deviation: 0.007



Selected sensors: 3, 7, 8, 10, 11

Test accuracy: 0.911 Test accuracy: 0.92 Test accuracy: 0.919 Test accuracy: 0.923 Test accuracy: 0.925 Mean accuracy: 0.919 Standard deviation: 0.005



Selected sensors: 2, 4, 6, 5, 9, 7

Test accuracy: 0.94 Set 2,4,6,9,5 and 7 Test accuracy: 0.926 Test accuracy: 0.931 Test accuracy: 0.93 Test accuracy: 0.934 Mean accuracy: 0.932 Standard deviation: 0.005

ONLY 8 SENSORS COMBINATIONS

Selected sensors: 1, 2, 4, 5, 6, 9, 12, 3

Test accuracy: 0.958 Set 1,2
Test accuracy: 0.953
Test accuracy: 0.951
Test accuracy: 0.953
Test accuracy: 0.95
Mean accuracy: 0.953
Standard deviation: 0.003




Selected sensors: 1, 2, 4, 5, 6, 9, 12, 8 Test accuracy: 0.049 Set 1,2,4,5,6,9,12 and 8

Test accuracy: 0.949
Test accuracy: 0.958
Test accuracy: 0.955
Test accuracy: 0.949
Test accuracy: 0.953
Mean accuracy: 0.953
Standard deviation: 0.004



Selected sensors: 1, 2, 4, 5, 6, 9, 12, 7 Test accuracy: 0, 949 Set 1,2,4,5,6,9,12 and 7

Test accuracy: 0.949
Test accuracy: 0.943
Test accuracy: 0.954
Test accuracy: 0.95
Test accuracy: 0.954
Mean accuracy: 0.95
Standard deviation: 0.004




Selected sensors: 1, 2, 4, 5, 6, 9, 8, 11

Test accuracy: 0.937
Test accuracy: 0.946
Test accuracy: 0.944
Test accuracy: 0.945
Test accuracy: 0.944
Mean accuracy: 0.943
Standard deviation: 0.003



Selected sensors: 1, 2, 4, 5, 6, 9, 12, 11


Test accuracy: 0.955
Test accuracy: 0.943
Test accuracy: 0.957
Test accuracy: 0.951
Test accuracy: 0.937
Mean accuracy: 0.949
Standard deviation: 0.008



ONLY 10 SENSORS COMBINATIONS

Selected sensors: 1, 12, 2, 5, 4, 6, 9, 3, 7, 10

Test accuracy: 0.955 Test accuracy: 0.971 Test accuracy: 0.97 Test accuracy: 0.967 Mean accuracy: 0.966



Selected sensors: 1, 12, 2, 5, 4, 6, 9, 7, 8, 10

Test accuracy: 0.965 Set 1,12,2,5,4,6,9,3,7 and Test accuracy: 0.969 Set 1,12,2,5,4,6,9,7,8 and 10

Test accuracy: 0.967 Test accuracy: 0.955 Test accuracy: 0.959 Test accuracy: 0.968 Mean accuracy: 0.964 Standard deviation: 0.006



Selected sensors: 1, 12, 2, 5, 4, 6, 9, 3, 8, 10

Test accuracy: 0.968 Test accuracy: 0.964

Test accuracy: 0.961^{Set} 1,12,2,5,4,6,9,3,8 and 10

Test accuracy: 0.96 Test accuracy: 0.961 Mean accuracy: 0.963 Standard deviation: 0.003




Selected sensors: 8, 11, 2, 5, 4, 6, 9, 3, 7, 10

Test accuracy: 0.961 Test accuracy: 0.957

Test accuracy: 0.967

Test accuracy: 0.957 Test accuracy: 0.961

Mean accuracy: 0.961 Standard deviation: 0.004




Set 8,11,2,5,4,6,9,3,7 and 10

ALL 12 SENSORS

Test accuracy: 0.971
Test accuracy: 0.968
Test accuracy: 0.963
Test accuracy: 0.969
Test accuracy: 0.977
Mean accuracy: 0.97
Standard deviation: 0.005

All sensors



USE OF SINGLE SENSORS

SENSOR 1

Test accuracy for sensor 1: 0.457 Test accuracy for sensor 1: 0.457 Test accuracy for sensor 1: 0.461 Test accuracy for sensor 1: 0.468 Test accuracy for sensor 1: 0.473 Mean accuracy for sensor 1: 0.463 Standard deviation for sensor 1: 0.007





SENSOR 2

Test accuracy for sensor 2: 0.477 Test accuracy for sensor 2: 0.488 Test accuracy for sensor 2: 0.485 Test accuracy for sensor 2: 0.487 Test accuracy for sensor 2: 0.481 Mean accuracy for sensor 2: 0.484 Standard deviation for sensor 2: 0.004

Sensor 2



SENSOR 3

Test accuracy for sensor 3: 0.629 Test accuracy for sensor 3: 0.654 Test accuracy for sensor 3: 0.645 Test accuracy for sensor 3: 0.636 Test accuracy for sensor 3: 0.659 Mean accuracy for sensor 3: 0.645 Standard deviation for sensor 3: 0.011

Sensor 3



SENSOR 4

Test accuracy for sensor 4: 0.429
Test accuracy for sensor 4: 0.437
Test accuracy for sensor 4: 0.411
Test accuracy for sensor 4: 0.44
Test accuracy for sensor 4: 0.425
Mean accuracy for sensor 4: 0.428
Standard deviation for sensor 4: 0.01



SENSOR 5

Test accuracy for sensor 5: 0.502
Test accuracy for sensor 5: 0.507
Test accuracy for sensor 5: 0.521
Test accuracy for sensor 5: 0.506
Test accuracy for sensor 5: 0.497
Mean accuracy for sensor 5: 0.507
Standard deviation for sensor 5: 0.008





SENSOR 6

Test accuracy for sensor 6: 0.448
Test accuracy for sensor 6: 0.441
Test accuracy for sensor 6: 0.453
Test accuracy for sensor 6: 0.45
Test accuracy for sensor 6: 0.443
Mean accuracy for sensor 6: 0.447
Standard deviation for sensor 6: 0.004

Sensor 6




SENSOR 7

Test accuracy for sensor 7: 0.56 Test accuracy for sensor 7: 0.564 Test accuracy for sensor 7: 0.578

Test accuracy for sensor 7: 0.554

Test accuracy for sensor 7: 0.563 Mean accuracy for sensor 7: 0.564

Standard deviation for sensor 7: 0.008



SENSOR 8

Test accuracy for sensor 8: 0.405 Test accuracy for sensor 8: 0.433 Test accuracy for sensor 8: 0.429

Test accuracy for sensor 8: 0.418

Test accuracy for sensor 8: 0.394 Mean accuracy for sensor 8: 0.416

Standard deviation for sensor 8: 0.015





SENSOR 9

Test accuracy for sensor 9: 0.47 Test accuracy for sensor 9: 0.479

Test accuracy for sensor 9: 0.487

Test accuracy for sensor 9: 0.463

Test accuracy for sensor 9: 0.471

Mean accuracy for sensor 9: 0.474 Standard deviation for sensor 9: 0.008 Sensor 9



SENSOR 10

Test accuracy for sensor 10: 0.473
Test accuracy for sensor 10: 0.47
Test accuracy for sensor 10: 0.473
Test accuracy for sensor 10: 0.477
Test accuracy for sensor 10: 0.475
Mean accuracy for sensor 10: 0.474
Standard deviation for sensor 10: 0.003



SENSOR11

Test accuracy for sensor 11: 0.457
Test accuracy for sensor 11: 0.449
Test accuracy for sensor 11: 0.466
Test accuracy for sensor 11: 0.436
Test accuracy for sensor 11: 0.473
Mean accuracy for sensor 11: 0.456
Standard deviation for sensor 11: 0.013



SENSOR 12

Test accuracy for sensor 12: 0.542
Test accuracy for sensor 12: 0.538
Test accuracy for sensor 12: 0.544
Test accuracy for sensor 12: 0.553
Test accuracy for sensor 12: 0.568
Mean accuracy for sensor 12: 0.549
Standard deviation for sensor 12: 0.011

