

NOTE: THE 2 BOLT FLANGE BEARINGS ARE SELF ALIGNING. BEFORE ASSEMBLY, SLIP SHAFT THROUGH BEARING AND SQUARE SHAFT TO MACHINED SURFACE ON THE CAST IRON BASE OF THE BEARINGS.

USE RED THREADLOCKER ON TIMING PULLEYS AND GEAR SET SCREWS. YOU CAN OPTIONALLY USE THE RED THREADLOCKER ON THE SHAFTS TO ADD RELIABILITY. NONE IS REQUIRED ON THE BEARINGS.

OTHERWISE SPECIFIED		MACHINING	WELDING	FABRICATING	FINISH REQUIREMENTS	USED ON REFERENCE MACHINE/DRAWING:	
	DECIMAL	.03, .005	.13	.06			
	ANGLE						
THE INFORMATION CONTAINED IN	THIS DRAWING	G IS THE SOLE PROF	PERTY OF PRECISIO	N PLASMA LLC. ANY	REPRODUCTION IN PART OR WHO	LE WITHOUT WRITTEN PERMISSION IS PROHIBITED.	
	SCALE:	1:2	SIZE: B	DATE	NAME	MATERIAL:	
	UNITS: INCHES		DRAWN	12/24/14	RWC		
	SOLIDS (Y/N): Y	CHECKED				
PRECISION		HD CARRIAGE REDUCTION			DRAWING NUMBER: REV.		
	_					CAD DED SHEET]	

PLASMA LLC.

CAR RED