











STEP 1.
CHECK MAIN PLATE TO
VERIFY THAT IT IS SQUARE.
ADJUST WITH HAMMER IF
NECESSARY.

OTHERWISE SPECIFIED		MACHINING	WELDING	FABRICATING	FINISH REQUIREMENTS	USED ON REFERENCE MACHINE/DRAW	ING:
	DECIMAI	.03, .005	.13	.06			
	ANGLE						
THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF PRECISION PLASMA LLC. ANY REPRODUCTION IN PART OR WHOLE WITHOUT WRITTEN PERMISSION IS PROHIBITED.							
	SCALE:	1:2	SIZE: <b>B</b>	DATE	NAME	MATERIAL:	
	UNITS: INCHES		DRAWN	7/15/17	RWC		
	SOLIDS (	Y/N): Y	CHECKED				
PRECISION		TITLE:	N A A			DRAWING NUMBER:	REV.
LKECISION		MAGNUM 7					CLIEFT 1

PRECISION PLASMA LLC. MAGNUM 7
CARRIAGE WELDMENT

MAG7-01

SHEET 1