

Vaartlaan 20

B-9800 Deinze



#### **CALIBRATION CERTIFICATE** RDE150006-D4E02 -EP080021.020

#### L.E.T. AUTOMOTIVE NV certifies that the electronical accuracy of the following appliance:

Appliance:

**SPEEDOSCOPE** 

serial number:

EP080021.020

Manufacturer:

L.E.T. AUTOMOTIVE NV, Vaartlaan 20, 9800 Deinze, Belgium

Client:

DSA - DRIVING STANDARDS AGENCY

is tested and calibrated conform the L.E.T. Automotive NV – directive :

060392E00-G3N01\_: Speedoscope electronical accuracy after refurbishing.

Using standards whose accuracies are traceable to National Standards or have been derived by the ratio type of self-calibration technics.

#### Calibration criteria:

Photocell distance

Maximum deviation

Measured deviation

[mm]

[mm]

Distance between cell 1 and cell 2 has to be 600 mm.

±1

0.504

Calibration equipment

Speedocal R0025

Software version: v2.0

Measurement uncertainty: ±0,05%

Speedoscope calibre R0030

Measurement uncertainty: ±0,005mm

Date of calibration

27/06/2019

Calibration valid till

27/06/2020

This certificate may not be reproduced other than in full, except with the permission of L.E.T. Automotive NV. Certificates without signature and stamp are not valid.

LET AUTOMOTIVE nv

Vaartlaan 20 - B-9800 Deinze Belgium Tel. +32 9 381 87 87

Fax +32 9 386 92 00

Date

27/06/2019

Stamp

L.E.T. Automotive NV

Email: info@let.be

Signature

Mr. J. Vandenberghe **Quality Manager** 

L.E.T. Automotive NV

Tel: +32-9-381 87 87 Fax: +32-9-386 92 00 Certificate id.: RDE150006-D4E02\_EP080021.020

Website : www.let.be Page 1/4



n.v. Vaartlaan 20

B-9800 Deinze



## Luminoscope

SPEEDOCAL R0025
SPEEDOCAL V2.00 DSA soft.: \* = round off: X,4 = X; X,5 up to X,9 = X+1

Fault on SPEEDOCAL: SPEEDOCAL: SpeedoscopeCalibre : R0030

Fault SpeedoscopeCalibre ±0,005 mm

Measured Difference 0,504mm

Speed generated by speedocal	Fault on speedocal	Serial speed by speedoscope	Speed displayed* on speedoscope	Difference speedocal and speedoscope		
				Permitted fault (cf. tolerance formula & fault speedocal)	Measured fault on serial speed speedoscope	Test criteria
km/h	km/h	km/h	km/h	km/h	km/h	OK/NOK
10	0,005	10,0	10	0,2	0,0	ОК
11	0,006	11,0	11	0,2	0,0	OK
12	0,006	12,0	12	0,2	0,0	OK
13	0,007	13,0	13	0,2	0,0	ОК
14	0,007	14,0	14	0,2	0,0	OK
15	0,008	15,0	15	0,2	0,0	OK
16	0,008	16,0	16	0,2	0,0	OK
17	0,009	17,0	17	0,2	0,0	OK
18	0,009	18,0	18	0,2	0,0	OK
19	0,010	19,0	19	0,2	0,0	OK
20	0,010	20,0	20	0,2	0,0	OK
21	0,011	21,0	21	0,2	0,0	OK
22	0,011	22,0	22	0,2	0,0	OK
23	0,012	23,0	23	0,2	0,0	ОК
24	0,012	24,0	24	0,2	0,0	OK
25	0,013	25,0	25	0,2	0,0	ОК
26	0,013	26,0	26	0,2	0,0	ОК
27	0,014	27,0	27	0,2	0,0	ОК
28	0,014	28,0	28	0,2	0,0	ОК
29	0,015	29,0	29	0,2	0,0	OK
30	0,015	30,0	30	0,2	0,0	ОК
31	0,016	31,0	31	0,2	0,0	OK
32	0,016	32,0	32	0,2	0,0	ОК
33	0,017	33,0	33	0,2	0,0	ОК
34	0,017	33,9	34	0,2	0,1	OK
35	0,018	35,0	35	0,2	0,0	OK
36	0,018	36,0	36	0,2	0,0	OK
37	0,019	37,0	37	0,2	0,0	ОК
38	0,019	37,9	38	0,2	0,1	ОК
39	0,020	39,0	39	0,2	0,0	ОК

Tel: +32-9-381 87 87 Fax: +32-9-386 92 00 Email: info@let.be Website: www.let.be
Certificate id: RDE150006-D4E02\_EP080021.020 Page 2/4



Vaartlaan 20 n.v.

B-9800 Deinze

# ISO 9001

## Luminoscope

40		- 8		_			INTERNATIONAL
42         0,021         41,9         42         0,2         0,1         OK           43         0,022         43,0         43         0,2         0,0         OK           44         0,022         43,9         44         0,2         0,1         OK           45         0,023         44,9         45         0,2         0,1         OK           46         0,023         46,0         46         0,2         0,0         OK           47         0,024         47,0         47         0,2         0,0         OK           48         0,024         48,0         48         0,2         0,0         OK           49         0,025         49,9         50         0,2         0,1         OK           50         0,026         50,9         51         0,2         0,1         OK           51         0,026         50,9         51         0,2         0,1         OK           52         0,026         52,0         52         0,2         0,0         OK           53         0,027         53,0         53         0,2         0,0         OK           54         0,027	40	0,020	39,9	40	0,2	0,1	ОК
43         0,022         43,0         43         0,2         0,0         OK           44         0,022         43,9         44         0,2         0,1         OK           45         0,023         44,9         45         0,2         0,1         OK           46         0,023         46,0         46         0,2         0,0         OK           47         0,024         47,0         47         0,2         0,0         OK           48         0,024         48,0         48         0,2         0,0         OK           49         0,025         49,0         49         0,2         0,0         OK           50         0,025         49,9         50         0,2         0,1         OK           51         0,026         50,9         51         0,2         0,1         OK           51         0,026         52,0         52         0,2         0,1         OK           52         0,026         52,0         52         0,2         0,0         OK           53         0,027         54,0         54         0,2         0,0         OK           55         0,028	41	0,021	41,0	41	0,2	0,0	OK
44         0,022         43,9         44         0,2         0,1         OK           45         0,023         44,9         45         0,2         0,1         OK           46         0,023         46,0         46         0,2         0,0         OK           47         0,024         47,0         47         0,2         0,0         OK           48         0,024         48,0         48         0,2         0,0         OK           49         0,025         49,0         49         0,2         0,0         OK           50         0,025         49,9         50         0,2         0,1         OK           51         0,026         50,9         51         0,2         0,1         OK           51         0,026         52,0         52         0,2         0,0         OK           52         0,026         52,0         52         0,2         0,0         OK           53         0,027         53,0         53         0,2         0,0         OK           54         0,027         54,0         54         0,2         0,0         OK           55         0,028	42	0,021	41,9	42	0,2	0,1	ОК
45 0,023 44,9 45 0,2 0,1 OK 46 0,023 46,0 46 0,2 0,0 OK 47 0,024 47,0 47 0,2 0,0 OK 48 0,024 48,0 48 0,2 0,0 OK 49 0,025 49,9 50 0,2 0,1 OK 51 0,026 50,9 51 0,2 0,1 OK 52 0,026 52,0 52 0,2 0,0 OK 53 0,027 53,0 53 0,2 0,0 OK 56 0,028 55,1 55 0,2 0,1 OK 56 0,028 55,1 55 0,2 0,1 OK 57 0,029 56,9 57 0,2 0,1 OK 58 0,029 57,9 58 0,2 0,1 OK 59 0,030 59,9 60 0,2 0,1 OK 60 0,030 59,9 60 0,2 0,1 OK 61 0,031 61,0 61 0,6 0,0 OK 62 0,031 62,0 62 0,6 0,0 OK 63 0,032 64,0 64 0,6 0,0 OK 66 0,033 65,0 66 0,2 OK 66 0,033 65,0 66 0,0 OK 66 0,033 66,0 64 0,6 0,0 OK 66 0,033 66,0 64 0,6 0,0 OK 67 0,034 67,1 67 0,6 0,0 OK 68 0,035 69,9 63 0,6 0,1 OK 69 0,035 69,9 60 0,2 OK 69 0,030 65,0 66 0,0 OK 61 0,031 62,0 62 0,6 0,0 OK 62 0,031 62,0 62 0,6 0,0 OK 63 0,032 64,0 64 0,6 0,0 OK 64 0,032 64,0 64 0,6 0,0 OK 65 0,033 66,2 66 0,6 0,0 OK 66 0,033 66,2 66 0,6 0,0 OK 67 0,034 67,1 67 0,6 0,1 OK 68 0,035 69,2 69 0,7 0,2 OK 69 0,036 72,1 72 0,0 OK 69 0,037 73,0 73 0,7 0,0 OK 69 0,038 74,8 75 0,7 0,2 OK 76 0,038 74,8 75 0,7 0,2 OK 77 0,039 77,0 77 0,7 0,0 OK 78 0,039 77,8 78 0,0 OK 69 0,040 78,7 79 0,8 0,3 OK	43	0,022	43,0	43	0,2	0,0	ОК
46 0,023 46,0 46 0,2 0,0 OK 47 0,024 47,0 47 0,2 0,0 OK 48 0,024 48,0 48 0,2 0,0 OK 49 0,025 49,0 49 0,2 0,0 OK 50 0,025 49,9 50 0,2 0,1 OK 51 0,026 50,9 51 0,2 0,0 OK 53 0,027 53,0 53 0,2 0,0 OK 54 0,027 54,0 54 0,2 0,0 OK 56 0,028 55,1 55 0,2 0,1 OK 57 0,029 56,9 57 0,2 0,1 OK 58 0,028 55,0 56 0,2 0,1 OK 59 0,030 59,0 59 0,2 0,1 OK 60 0,030 59,9 60 0,2 0,1 OK 61 0,031 61,0 61 0,6 0,0 OK 63 0,032 62,9 63 0,6 0,1 OK 64 0,032 64,0 64 0,6 0,0 OK 65 0,033 65,0 65 0,6 0,0 OK 66 0,030 65,0 66 0,0 OK 66 0,030 65,0 66 0,0 OK 66 0,030 65,9 60 0,2 O,1 OK 66 0,031 62,0 62 0,6 0,0 OK 66 0,033 65,0 66 0,0 OK 67 0,034 67,1 67 0,6 0,0 OK 68 0,035 69,2 69 0,7 0,2 OK 69 0,036 72,1 71 71 0,7 0,1 OK 69 0,037 73,0 73,0 73 0,7 0,0 OK 71 0,038 74,8 75 0,7 0,2 OK 79 0,040 78,7 79 0,8 0,3 OK 79 0,040 78,7 79 0,8 0,3 OK 79 0,040 78,7 79 0,8 0,2 OK 79 0,040 78,7 79 0,8 0,3 OK 79 0,040 78,7 79 0,8 0,3 OK	44	0,022	43,9	44	0,2	0,1	ОК
47 0,024 47,0 47 0,2 0,0 OK 48 0,024 48,0 48 0,2 0,0 OK 49 0,025 49,0 49 0,2 0,0 OK 50 0,025 49,9 50 0,2 0,1 OK 51 0,026 52,0 52 0,2 0,0 OK 53 0,027 53,0 53 0,2 0,0 OK 54 0,027 54,0 54 0,2 0,0 OK 55 0,028 55,1 55 0,2 0,1 OK 57 0,029 56,9 57 0,2 0,1 OK 58 0,028 56,0 56 0,2 0,0 OK 59 0,030 59,0 59 0,2 0,1 OK 60 0,030 59,0 59 0,2 0,1 OK 61 0,031 61,0 61 0,6 0,0 OK 64 0,032 64,0 64 0,6 0,0 OK 65 0,033 65,0 66 0,2 O,6 OK 66 0,033 66,2 66 0,6 0,0 OK 66 0,033 66,2 66 0,6 0,2 OK 67 0,034 67,1 67 0,6 0,1 OK 68 0,035 74,3 74,3 74 0,7 0,3 OK 75 0,039 77,0 77 0,7 0,0 OK 77 0,039 77,0 77 0,7 0,0 OK 78 0,039 77,8 78 0,2 OK 79 0,030 79,7 79 0,8 0,3 OK 77 0,039 77,0 77 0,7 0,0 OK 78 0,039 77,8 78 0,2 OK 79 0,039 77,8 78 0,2 OK 79 0,040 78,7 79 0,8 0,3 OK	45	0,023	44,9	45	0,2	0,1	ОК
48 0,024 48,0 48 0,2 0,0 OK 49 0,025 49,0 49 0,2 0,0 OK 50 0,025 49,9 50 0,2 0,1 OK 51 0,026 50,9 51 0,2 0,0 OK 52 0,026 52,0 52 0,2 0,0 OK 53 0,027 53,0 53 0,2 0,0 OK 55 0,028 55,1 55 0,2 0,1 OK 56 0,028 56,0 56 0,2 0,1 OK 57 0,029 56,9 57 0,2 0,1 OK 58 0,029 57,9 58 0,2 0,1 OK 59 0,030 59,0 59 0,2 0,0 OK 60 0,030 59,9 60 0,2 0,1 OK 61 0,031 61,0 61 0,6 0,0 OK 62 0,031 62,0 62 0,6 0,0 OK 63 0,032 62,9 63 0,6 0,1 OK 64 0,032 64,0 64 0,6 0,0 OK 65 0,033 65,0 65 0,6 0,0 OK 66 0,033 65,0 65 0,6 0,1 OK 66 0,033 65,0 65 0,6 0,0 OK 67 0,034 67,9 68 0,6 0,1 OK 69 0,035 69,2 69 0,7 0,2 OK 69 0,035 69,9 70 0,7 0,1 OK 69 0,036 71,1 71 0,7 0,1 OK 71 0,036 71,1 71 0,7 0,1 OK 73 0,037 73,0 73 0,7 0,0 OK 74 0,037 74,3 74 0,7 0,3 OK 75 0,039 77,0 77 0,2 OK 76 0,039 77,0 77 0,2 OK 77 0,039 77,0 77 0,2 OK 78 0,039 77,8 78 0,7 0,2 OK 79 0,040 78,7 79 0,8 0,3 OK	46	0,023	46,0	46	0,2	0,0	ОК
49         0,025         49,0         49         0,2         0,0         OK           50         0,025         49,9         50         0,2         0,1         OK           51         0,026         50,9         51         0,2         0,1         OK           52         0,026         52,0         52         0,2         0,0         OK           53         0,027         53,0         53         0,2         0,0         OK           54         0,027         54,0         54         0,2         0,0         OK           55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           61         0,031         61,0         61         0,6         0,0         OK           61         0,031	47	0,024	47,0	47	0,2	0,0	ОК
50         0,025         49,9         50         0,2         0,1         OK           51         0,026         50,9         51         0,2         0,1         OK           52         0,026         52,0         52         0,2         0,0         OK           53         0,027         53,0         53         0,2         0,0         OK           54         0,027         54,0         54         0,2         0,0         OK           55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           56         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031	48	0,024	48,0	48	0,2	0,0	ОК
51         0,026         50,9         51         0,2         0,1         OK           52         0,026         52,0         52         0,2         0,0         OK           53         0,027         53,0         53         0,2         0,0         OK           54         0,027         54,0         54         0,2         0,0         OK           55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032	49	0,025	49,0	49	0,2	0,0	ОК
52         0,026         52,0         52         0,2         0,0         OK           53         0,027         53,0         53         0,2         0,0         OK           54         0,027         54,0         54         0,2         0,0         OK           55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         64,0         64         0,6         0,0         OK           64         0,033	50	0,025	49,9	50	0,2	0,1	ОК
53         0,027         53,0         53         0,2         0,0         OK           54         0,027         54,0         54         0,2         0,0         OK           55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           61         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033	51	0,026	50,9	51	0,2	0,1	ОК
54         0,027         54,0         54         0,2         0,0         OK           55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033	52	0,026	52,0	52	0,2	0,0	ОК
55         0,028         55,1         55         0,2         0,1         OK           56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,1         OK           67         0,034	53	0,027	53,0	53	0,2	0,0	ОК
56         0,028         56,0         56         0,2         0,0         OK           57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034	54	0,027	54,0	54	0,2	0,0	ОК
57         0,029         56,9         57         0,2         0,1         OK           58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035	55	0,028	55,1	55	0,2	0,1	ОК
58         0,029         57,9         58         0,2         0,1         OK           59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,036	56	0,028	<del>56,</del> 0	56	0,2	0,0	ОК
59         0,030         59,0         59         0,2         0,0         OK           60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,036         71,1         71         0,7         0,1         OK           72         0,036	57	0,029	56,9	57	0,2	0,1	ОК
60         0,030         59,9         60         0,2         0,1         OK           61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036	58	0,029	57,9	58	0,2	0,1	ОК
61         0,031         61,0         61         0,6         0,0         OK           62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037	59	0,030	59,0	59	0,2	0,0	ОК
62         0,031         62,0         62         0,6         0,0         OK           63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037	60	0,030	59,9	60	0,2	0,1	ОК
63         0,032         62,9         63         0,6         0,1         OK           64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038	61	0,031	61,0	61	0,6	0,0	ОК
64         0,032         64,0         64         0,6         0,0         OK           65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,039	62	0,031	62,0	62	0,6	0,0	OK
65         0,033         65,0         65         0,6         0,0         OK           66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039	63	0,032	62,9	63	0,6	0,1	OK
66         0,033         66,2         66         0,6         0,2         OK           67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040	64	0,032	64,0	64	0,6	0,0	ОК
67         0,034         67,1         67         0,6         0,1         OK           68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040	65	0,033	65,0	65	0,6	0,0	OK
68         0,034         67,9         68         0,6         0,1         OK           69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	66	0,033	66,2	66	0,6	0,2	ОК
69         0,035         69,2         69         0,7         0,2         OK           70         0,035         69,9         70         0,7         0,1         OK           71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	67	0,034	67,1	67	0,6	0,1	OK
70         0,035         69,9         70         0,7         0,1         0K           71         0,036         71,1         71         0,7         0,1         0K           72         0,036         72,1         72         0,7         0,1         0K           73         0,037         73,0         73         0,7         0,0         0K           74         0,037         74,3         74         0,7         0,3         0K           75         0,038         74,8         75         0,7         0,2         0K           76         0,038         76,2         76         0,7         0,2         0K           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	68	0,034	67,9	68	0,6	0,1	OK
71         0,036         71,1         71         0,7         0,1         OK           72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	69	0,035	69,2	69	0,7	0,2	OK
72         0,036         72,1         72         0,7         0,1         OK           73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	70	0,035	69,9	70	0,7	0,1	OK
73         0,037         73,0         73         0,7         0,0         OK           74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	71	0,036	71,1	71	0,7	0,1	OK
74         0,037         74,3         74         0,7         0,3         OK           75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	72	0,036	72,1	72	0,7	0,1	OK
75         0,038         74,8         75         0,7         0,2         OK           76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	73	0,037	73,0	73	0,7	0,0	OK
76         0,038         76,2         76         0,7         0,2         OK           77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK	74	0,037	74,3	74	0,7	0,3	OK
77         0,039         77,0         77         0,7         0,0         OK           78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK		0,038	74,8	75	0,7	0,2	OK
78         0,039         77,8         78         0,7         0,2         OK           79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK		0,038	76,2	76	0,7	0,2	ОК
79         0,040         78,7         79         0,8         0,3         OK           80         0,040         80,2         80         0,8         0,2         OK		0,039	77,0	77	0,7	0,0	OK
80 0,040 80,2 80 0,8 0,2 OK	78	0,039	77,8	78	0,7	0,2	OK
5,5	79	0,040	78,7	79	0,8	0,3	ОК
81 0.041 80.9 81 0.8 0.1	80	0,040	80,2	80	0,8	0,2	ОК
0,0 U,1 UK	81	0,041	80,9	81	0,8	0,1	ОК

Tel: +32-9-381 87 87 Fax: +32-9-386 92 00 Certificate id.: RDE150006-D4E02\_EP080021.020

Email: info@let.be

Website : www.let.be
Page 3/4



n.v. Vaartlaan 20

B-9800 Deinze



## Luminoscope

82	0,041	82,4	82	8,0	0,4	OK
83	0,042	82,8	83	8,0	0,2	ОК
84	0,042	83,9	84	0,8	0,1	OK
85	0,043	85,2	85	0,8	0,2	ОК
86	0,043	85,9	86	8,0	0,1	OK
87	0,044	86,8	87	0,8	0,2	ОК
88	0,044	88,4	88	0,8	0,4	ОК
89	0,045	89,3	89	8,0	0,3	ОК
90	0,045	90,3	90	0,9	0,3	ОК
91	0,046	91,0	91	0,9	0,0	ОК
92	0,046	92,3	92	0,9	0,3	ОК
93	0,047	93,0	93	0,9	0,0	ОК
94	0,047	94,4	94	0,9	0,4	ОК
95	0,048	95,3	95	0,9	0,3	OK
96	0,048	96,1	96	0,9	0,1	OK
97	0,049	97,1	97	0,9	0,1	OK
98	0,049	98,3	98	0,9	0,3	OK
99	0,050	99,0	99	0,9	0,0	OK

Tel: +32-9-381 87 87 Fax: +32-9-386 92 00 Email: info@let.be Website: www.let.be
Certificate id.: RDE150006-D4E02\_EP080021.020 Email: info@let.be