Bode Diagram Gm = Inf, Pm = -41 deg (at 0.869 rad/s) 100 50 Magnitude (dB) -50 -100 Drs- (ded) -240 Frequency (rad/s)