

HungaroControl AIRAC AMDT 005/2021

AD 2 LHSM INSTRUMENT APPROACH CHART NDB RWY 16

NDB approach procedure:

Initial altitude at or above 4000. Leave SME NDB on QDR 305 SME and descend 2100. Aft D 9.5 SME turn right and join CW D 9.5 SME DME arc.

After crossing LQDR 328 SME leading QDR turn right and intercept QDM 160 SME (final track), descend 1700.

When crossing D 5.8 SME (FAF) descend to published minimum altitude.

Holding procedure: Holding fix: SME NDB. Left hand holding pattern.

Maximum speed: 210 KIAS 355° Inbound track: Outbound track: 175°

3°/sec. or 25° bank angle (whichever requires lesser bank) Rate of turn:

Outbound timing: 1 min Minimum holding altitude: 4000

HungaroControl 4 **AIRAC AMDT 005/2021**

