

HungaroControl AIRAC AMDT 005/2021

## AD 2 LHSM INSTRUMENT APPROACH CHART NDB RWY 34

## NDB approach procedure:

Initial altitude at or above 4000. Leave SME NDB on QDR 202 SME and descend 2600. At D 7.2 SME turn left and join CCW D 7.2 SME DME arc.

After crossing LQDR 176 SME leading QDR turn left and intercept QDM 340 SME (final track), descend 1700.

When crossing D 3.3 SME DME (FAF) descend to published minimum altitude.

Holding procedure: Holding fix: SME NDB. Right hand holding pattern.

210 KIAS 142° Maximum speed: Inbound track: 322° Outbound track:

3°/sec. or 25° bank angle (whichever requires lesser bank) Rate of turn:

Outbound timing: 1 min Minimum holding altitude: 4000

HungaroControl 4 **AIRAC AMDT 005/2021** 

