


2 I rouble	shooting	IP-10: Error codes 20, 30	2 - 56
LCx [®] A	nalyzer Service Manual (Text P/N 47278-102)	·	

Chapter Manual CD Main Index Contents Contents Screen

IP-10 (pg 2 of 5)




2	Troubleshooting	IP-10: Error codes 20, 30	2 - 57
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP-10 (pg 3 of 5) Νo Perform Carousel Sensor CV >3 Move Carousel to Adjustment (VP-34). locked position: Yes **99** Carefully unlock ■ STORE Νo Check Carousel while ■ CW (2 times) Νo passes holding it in place. CV <2 **4**0 ■ STORE Yes

C W

Yes




Chapter Manual CD Main Index Contents Contents Screen

Normal operation

IP10-3.vsd


IP-10 (pg 4 of 5)



Troubleshooting	IP-10: Error codes 20, 30	2 - 59
LCx [®] Analyzer Service Manual (Text P/N 47278-102)		

	O Main Index creen
--	--------------------

IP-10 (pg 5 of 5)



2	Troubleshooting	IP-10: Error codes 20, 30	2 - 60
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	