

IP-73 Error code 157 (pg 1 of 3)

EC-157: Current liquid temp out of spec



2 Troubleshooting IP-73: Error code 157 2 - 189 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	
Contonto	Contents	0010011	



that does not resolve the problem, re-install

that component before proceeding.

and Air Heater Assy


(RR-3.16).

2 Troubleshooting IP-73: Error code 157 2 - 190 LCx[®] Analyzer Service Manual (Text P/N 47278-102)

Chapter Manual Contents Contents	CD Main Screen	Index
----------------------------------	-------------------	-------

IP73-2.vsd

IP-73 (pg 3 of 3)



2 Troubleshooting IP-73: Error code 157 2 - 191 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter Manua Contents Conten	_	Index
----------------------------------	---	-------