
IP-46 Error code 103 (pg 1 of 1)

EC-103: Bad value in assay XX



IP46.vsd

2	Troubleshooting	IP-46: Error code 103	2 - 129
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	