
IP-68 Error code 142 (pg 1 of 4)

EC-142: Slope/Intercept out of range




2 Troubleshooting IP-68: Error code 142 2 - 172 LCx® Analyzer Service Manual (Text P/N 47278-102)

(1511)


Chapter Manual CD Main Index Contents Contents Screen

IP-68 (pg 2 of 4)



2	Troubleshooting	IP-68: Error code 142	2 - 173
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter Manual Contents Contents	CD Main Screen	Index
----------------------------------	-------------------	-------




then Digital I/O Bd (RR-7.10).

2 Troubleshooting IP-68: Error code 142 2 - 174 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP68-3.vsd

IP-68 (pg 4 of 4)



eration IP68-4.vsd

2 Troubleshooting IP-68: Error code 142 2 - 175 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	