
IP-70 Error codes 145, 146 (pg 1 of 7)

EC-145:M% difference out of specification

EC-146: H% difference out of specification



2 Troubleshooting IP-70: Error codes 145, 146 2 - 179 LCx® Analyzer Service Manual (Text P/N 47278-102)


Contents

Chapter

Manual Contents CD Main Screen

Index


IP-70 (pg 2 of 7)



2 Troubleshooting IP-70: Error codes 145, 146 2 - 180 LCx[®] Analyzer Service Manual (Text P/N 47278-102)

Chapter Manual CD Main Index Contents Screen


IP-70 (pg 3 of 7)



2 Troubleshooting IP-70: Error codes 145, 146 2 - 181 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter Manual Contents Contents	CD Main Screen	Index
----------------------------------	-------------------	-------


IP-70 (pg 4 of 7)



2 Troubleshooting IP-70: Error codes 145, 146 2 - 182 LCx[®] Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP-70 (pg 5 of 7)



2 - 183 **Troubleshooting** IP-70: Error codes 145, 146 LCx® Analyzer Service Manual (Text P/N 47278-102)


> Chapter Manual **CD Main** Contents Contents Screen

Νo

IP70-5.vsd

Index

IP-70 (pg 6 of 7)




IP70-6.vsd

2 Troubleshooting IP-70: Error codes 145, 146 2 - 184 LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP-70 (pg 7 of 7)



2 Troubleshooting IP-70: Error codes 145, 146 2 - 185 LCx[®] Analyzer Service Manual (Text P/N 47278-102)

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	