
IP-34 Error code 74 (pg 1 of 4)


EC-74: Bad High Voltage Power Supply



2	Troubleshooting	IP-34: Error code 74	2 - 115
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP-34 (pg 2 of 4)




NOTE: When a component is replaced and that does not resolve the problem, re-install that component before proceeding.

IP34-2.vsd

2 - 116 IP-34: Error code 74 **Troubleshooting** LCx® Analyzer Service Manual (Text P/N 47278-102)

Chapter Manual Contents Contents	CD Main Screen	Index
----------------------------------	-------------------	-------


IP-34 (pg 3 of 4)



Troubleshooting LCx [®] Analyzer Service Manual (Text P/N 47278-	102)	IP-34: Error	code 74	2 - 117

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

IP-34 (pg 4 of 4)



2	Troubleshooting LCx [®] Analyzer Service Manual (Text P/N 47278-102)	IP-34: Error code 74	2 - 118

Chapter	Manual	CD Main	Index
Contents	Contents	Screen	