
IP-47 Error code 104 (pg 1 of 1)

EC- 104: Assay revisions mismatch



2	Troubleshooting	IP-47: Error code 104	2 - 130
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter Manual Contents Contents	CD Main Screen	Index
----------------------------------	-------------------	-------