

## VP-62: FACTORY SET (pg 1 of 2)

Time: 2 hours

Purpose: To reset all parameters and start over from factory default settings

- 1. Print System File 1:
  - SYSTEM
  - FILES

  - PRINT
- 2. Repeat step 1 for System Files 2, 3, 30 and 31.

- Perform a Factory Reset:
  - UTILITY
  - OTHER
  - OTHER
  - SERVICE
  - OTHER 9617
  - FAC SET
  - ALL
  - 4. Perform IP-45.
- 5. Perform these service tests:
  - Printer Test (VP-41)
    - Keyboard Test (VP-42)Display Test (VP-43)
    - RS-232 Com Port Test (VP-44)

Verification Procedures
LCx<sup>®</sup> Analyzer Service Manual (Text P/N 47278-102)

•			
Chapter	Manual	CD Main	Index
Contents	Contents	Screen	

**VP-62: Factory Set** 

5 - 110

## VP-62: Factory Set (pg 2 of 2)

- 6. Perform these procedures:
  - MEIA Carousel Calibration (VP-30)
  - Matrix Detection (VP-32)
  - Boom Calibration (VP-8)
  - Dispense Check (VP-13)
  - MEIA Temperature Calibration (VP-29)
  - MEIA Initialization Photo Calibration (VP-27)
  - Bar Code Check (VP-4)

5	Verification Procedures	VP-62: Factory Set	5 - 111
	LCx® Analyzer Service Manual (Text P/N 47278-102)		

Chapter Contents
---------------------